

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2025

Submitted Date:

05/09/2025

Document Number:

718100518

FIELD INSPECTION FORM

Loc ID 490082 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

4 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 999 18TH STREET SUITE 1755N

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		geops@oxbow.com	Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
490082	LOCATION	AC	05/07/2025		-	Gunnison Tank 11S90W	RI

General Comment:

On 5/6/2025, Western Reclamation Work Lead Trujillo conducted an inspection at Gunnison Energy LLC's Gunnison Tank 11S90W facility Location in Gunnison County, Colorado.

The following compliance issues were observed during this inspection:

- Good Housekeeping
- Weeds
- Signage requirements

Refer to the Location sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Tank battery signage does not comport with Rule 605 requirements, and does not include information such as the well names and API number associated with the tank battery., and the legal location of the wells.		
Corrective Action:	Comply with Rule 605.e.	Date:	06/09/2025
Type	TANK LABELS/PLACARDS		
Comment:	Signage/labeling at tank does not comport with 605 requirements.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-874-7697	Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Undesirable and Noxious Plant Species (Common mullein and Musk thistle rosettes) observed established throughout the Location		
Corrective Action:	Comply with Rule 606.c. Oil and Gas Locations will be kept free of all Undesirable Plant Species.	Date:	05/24/2025
Type			
Comment:	Various trash, debris and unused equipment observed throughout the Location		
Corrective Action:	Comply with 606 rules.	Date:	05/16/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Sheep fencing		
Corrective Action:		Date:	

Equipment:

Type:	#		corrective date
Comment:	Riser on Location appears to be open to atmosphere, and missing cap or plug; hosing has been disconnected		
Corrective Action:	Install cap/plug at open pipe equipment.	Date:	05/16/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		
Comment:	<input type="text"/>				

Corrective Action:	Date:
--------------------	-------

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:	Containment berm damaged on the east end of the facility. It is not clear at time of inspection if BMP is in proper functioning condition. Maintenance advised.			
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			
			Date:

Flaring:

Type			
Comment:			
Corrective Action:			
			Date:

Inspected Facilities

Facility ID: 490082 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718100519	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7043022