

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2025

Submitted Date:

05/11/2025

Document Number:

708906464

FIELD INSPECTION FORM

Loc ID 323783 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10550
 Name of Operator: MUSTANG RESOURCES LLC
 Address: 3 GREENWAY PLAZA STE 1360
 City: HOUSTON State: TX Zip: 77046

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mustang		nwelch@venatorresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210798	WELL	PR	07/01/2024	GW	045-06556	MEAD 23-44-6S-94W	PR

General Comment:

[CECMC Inspection/Audit Report Summary](#)
 On 05/05/2025 at approximately 11:04 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad. Location # 323783 in Garfield County Colorado.
 Please refer to inspection 708906164 conducted on 03/31/2025, previous corrective actions have been completed. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to Bald Eagle Roost site & NSO Habitat area. Location is approximately 240 yards from Beaver Creek & approximately 575 yards from the Colorado River. While there, I observed normal production operations.
 This is a summary of inspection/audit report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Compressor engine oil tank		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/888-291-8588		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Compressor	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Compressor master meter		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	3 marked deadman & 1 improperly marked deadman - Improperly marked deadman was noted in previous inspection & remains unaddressed. All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Well is not on plunger lift		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Inlet scrubber/slug catcher		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter for the MEAD 23-44-6S-94W well		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Fire extinguisher		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Compressor engine oil
Other (Capacity)	500 gal

Other (Type) _____					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment: Separate containment					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,
Comment: Tank not equipped with telemetry					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) 210 bbl					
Other (Type) _____					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment: Separate containment					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 210798 Type: WELL API Number: 045-06556 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well not on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				Small amount of light compaction
Gravel						Sparse to none in areas
Compaction						Small amount of light compaction
		Gravel				Sparse to none in areas
Check Dams						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906465	Inspection/Audit 708906464 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7044296
708906466	Inspection/Audit 708906464 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7044297