

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 22-16 Pad

Location ID: 335522



Photo # 9911 From entrance to location




Photo # 9912 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 22-16 Pad

Location ID: 335522



Photo # 9913 Location



Photo # 9414 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 22-16 Pad

Location ID: 335522



Photo # 9915 Location



Photo # 9916 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 22-16 Pad

Location ID: 335522



Photo # 9917 Location



Photo # 9918 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY KP 22-16 Pad

Location ID: 335522



Photo # 9919 PRV vent line does not comply with CECMC pressure safety device rules or general safety rules



Photo # 9920 PRV vent line does not comply with CECMC pressure safety device rules or general safety rules