

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2025

Submitted Date:

05/05/2025

Document Number:

708906416

**FIELD INSPECTION FORM**

Loc ID 335234 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 3 GREENWAY PLAZA STE 1360

City: HOUSTON State: TX Zip: 77046

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Taylor Elm (CPW)		taylor.elm@state.co.us	
Mustang		nwelch@venatorresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210799	WELL	PR	07/01/2024	CBM	045-06557	MEAD 24-14MV-6S-94W	PR
210812	WELL	PR	01/01/2025	GW	045-06570	MEAD 24-14W-6S-94W	PR

**General Comment:**

[CECMC Inspection/Audit Report Summary](#)  
 On 05/05/2025 at approximately 11:25 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at MUSTANG RESOURCES LLC Mead 24-14MV Pad Location # 335234 in Garfield County Colorado.  
 Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site & in close proximity to NSO Habitat area.  
 Location is approximately 333 yards from Beaver Creek.  
 While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Tanks & Berms - Tank failure - Multiple holes in production tank/tank lacks integrity with a CA date of 05/07/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
 This is a summary of inspection/audit report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/888-291-8588		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 2		corrective date
Comment:	No form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		

Comment: MEAD 24-14MV-6S-94W well on plunger lift MEAD 24-14W-6S-94W well is not on plunger lift			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment: 5 Marked deadman 2 Improperly marked deadman - please refer to photo log  All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment: Tank not equipped with telemetry					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	90 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: Centralized containment				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		
Comment: Tank failure – Multiple holes in production tank/tank lacks integrity (Additionally the holes also constitute a wildlife hazard)					
Corrective Action: If tank is in service comply with CECMC rules for in-service tanks and process vessels or If tank is out of service comply with CECMC rules for out of service tanks and process vessels		Date:		05/07/2025	

<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)	210 bbl			
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Centralized containment			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 210799 Type: WELL API Number: 045-06557 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 210812 Type: WELL API Number: 045-06570 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well not on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Other						Small gravel stockpile on location
		Gravel				Sparse to none
		Compaction				
Gravel						Sparse to none in areas

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Tanks &amp; Berms for corrective action &amp; also refer to Equipment for comments.</a>	smelserw	05/05/2025
<a href="#">Additionally dead bird observed in secondary containment - please refer to photo log</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404191113	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7036241">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7036241</a>
708906417	Inspection/Audit 708906416 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7036239">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7036239</a>
708906418	Inspection/Audit 708906416 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7036240">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7036240</a>