

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

04/15/2024

Document Number:

403665291

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10633 Contact Person: James Miller
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 322848 Location Type: Production Facilities
Name: ANDERSON TRUST C UNIT PAD Number: 2
County: WELD
Qtr Qtr: NENW Section: 32 Township: 2N Range: 68W Meridian: 6
Latitude: 40.099570 Longitude: -105.031650

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 455481 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 336463 Location Type: Well Site   
Name: RAY NELSON MULTI-WELL PAD Number: 0-4-32  
County: WELD No Location ID  
Qtr Qtr: SWNW Section: 32 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.097180 Longitude: -105.034420

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000  
Bedding Material: \_\_\_\_\_ Date Construction Completed: 05/12/2013  
Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: \_\_\_\_\_  
Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 01/14/2019

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

Flowline was disconnected from wellhead and from separator. Flowline from separator to the north was abandoned in place beneath Anadarko gas lines, the other portion of the flowline to the well was removed from the ground. Flowline was plugged on both ends with 120lbs of slurry per State NTO.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 455470 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 336463 Location Type: Well Site   
Name: RAY NELSON MULTI-WELL PAD Number: 0-4-32  
County: WELD No Location ID  
Qtr Qtr: SWNW Section: 32 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.097180 Longitude: -105.034420

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000  
Bedding Material: \_\_\_\_\_ Date Construction Completed: 08/29/2011  
Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: \_\_\_\_\_  
Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 01/14/2019

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

Flowline was disconnected from wellhead and from separator. Flowline was flushed with 25bbls fresh water prior to abandonment. Verified with LEL monitor that line was free of hydrocarbons. Flowline from separator to the north was abandoned in place beneath Anadarko gas lines. The other portion of the flowline to the well was removed from the ground. Flowline was plugged on both ends with 120lbs of slurry per State NTO.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 455406 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 336463 Location Type: Well Site   
Name: RAY NELSON MULTI-WELL PAD Number: 0-4-32  
County: WELD No Location ID  
Qtr Qtr: SWNW Section: 32 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.097180 Longitude: -105.034420

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000  
Bedding Material: Date Construction Completed: 08/19/2011  
Maximum Anticipated Operating Pressure (PSI): Testing PSI:  
Test Date:

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 01/14/2019

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

Flowline was disconnected from wellhead and from separator. Flowline was flushed with 25bbls fresh water prior to abandonment. Verified with LEL monitor that line was free of hydrocarbons. Flowline from separator to the north was abandoned in place beneath Anadarko gas lines, the other portion of the flowline to the well was removed from the ground. Flowline was plugged on both ends with 120lbs of slurry per State NTO.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 465982 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 331652 Location Type: Well Site   
Name: FEDERAL NOAA-62N68W Number: 32NWNW  
County: WELD No Location ID

Qtr Qtr: NWNW Section: 32 Township: 2N Range: 68W Meridian: 6

Latitude: 40.100517 Longitude: -105.034617

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: Native Materials Date Construction Completed: 09/27/2003

Maximum Anticipated Operating Pressure (PSI): 1000 Testing PSI: \_\_\_\_\_

Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 01/11/2024

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline (12321062\_FL) serving the FEDERAL NOAA 11-32 (05-123-21062) was partially abandoned in place and partially removed. The segment from the wellhead to where the line meets the 6" Hub flowlines was removed 1/11/2024. The segment that crosses the 6" Hub flowlines to the county road was removed 3/29/2024. The segment along and under the county road was abandoned in place 3/29/2024. The remainder of the flowline to the separator was removed 3/29/2024. The flowline was abandoned in place as per Rule 1105.e. See attachments for third party verification and layout exhibit.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments Form 44 filed to report POST-ABANDONMENT verification. The following flowline(s) were partially abandoned in place and partially removed:  
12321062\_FL: serviced Federal NOAA 11-32 (05-123-21062)  
  
Pressure test attached.  
Third party verification attached.  
Layout exhibit attached.  
Updated GIS data attached.  
All other related flowlines will remain as previously reported.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 04/15/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_ Director of ECMC Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY LIST**

**COA Type**

**Description**

--	--

**ATTACHMENT LIST**

**Att Doc Num**

**Name**

403728428	PRESSURE TEST
403752772	THIRD PARTY VERIFICATION
403753485	PROPOSED ABANDONMENT LAYOUT DRAWING
403754706	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 4 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)