

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7136 Entrance to location



Photo # 7147 Location

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7137 Location



Photo # 7146 Location



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7164 Location



Photo # 7210 SE corner of location

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7211 SW corner of location



Photo # 7212 NW corner of location



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



May 7, 2025 at 3:23:21 PM  
+39.206627,-107.917397 ±3.50m  
Collbran

Photo # 7213 NE corner of location



May 7, 2025 at 2:40:05 PM  
+39.205957,-107.917430 ±6.54m  
Collbran

Photo # 7153 Multiple holes in both secondary containments on location liners/liners need maintenance



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7154 Multiple holes in both secondary containments on location liners/liners need maintenance**



**Photo # 7156 Multiple holes in both secondary containments on location liners/liners need maintenance**



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7157 Multiple holes in both secondary containments on location liners/liners need maintenance**



**Photo # 7158 Multiple holes in both secondary containments on location liners/liners need maintenance**

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7159 Multiple holes in both secondary containments on location liners/liners need maintenance**



**Photo # 7174 Multiple holes in both secondary containments on location liners/liners need maintenance**



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7175 Multiple holes in both secondary containments on location liners/liners need maintenance**



**Photo # 7176 Multiple holes in both secondary containments on location liners/liners need maintenance**



## Inspection/Audit Photos


Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7177 Multiple holes in both secondary containments on location liners/liners need maintenance**



**Photo # 7178 Multiple holes in both secondary containments on location liners/liners need maintenance**



## Inspection/Audit Photos


Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7179 Multiple holes in both secondary containments on location liners/liners need maintenance**



**Photo # 7180 Multiple holes in both secondary containments on location liners/liners need maintenance**

## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7143 Unused equipment



Photo # 7160 Unused equipment



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7162 Unused equipment




Photo # 7173 Unused equipment



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7170 Wildlife hazard



Photo # 7183 Unused flowline at tank battery lacks lockout tagout (OOSLAT)



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7184 Unused flowline near MWR 7-1A wellhead  
lacks lockout tagout (OOSLAT)**



**Photo # 7188 Unused flowline at separators lack lockout  
tagout (OOSLAT)**



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7189 Unused flowlines at separators lack lockout tagout (OOSLAT)**



**Photo # 7197 Unused flowlines near pump house lack lockout tagout (OOSLAT)**



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



**Photo # 7199 Unused flowlines near pump house lack lockout tagout (OOSLAT)**



**Photo # 7204 Unused flowlines at pump house lack lockout tagout (OOSLAT)**



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7208 Unused flowlines at pump house lack lockout tagout (OOSLAT)



Photo # 7223 Unused flowline at tank battery lacks lockout tagout (OOSLAT)



## Inspection/Audit Photos

Location: LARAMIE ENERGY LLC My Way Ranch/7-8 Pad

Location ID: 334514

Date: 05/7/2025



Photo # 7215 Debris on location



Photo # 7218 Debris on location