

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2025

Submitted Date:

05/12/2025

Document Number:

707801576

## FIELD INSPECTION FORM

 Loc ID 436676 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments  
 4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 ECMC Operator Number: 10805  
 Name of Operator: FULCRUM ENERGY OPERATING LLC  
 Address: 240 SAINT PAUL STREET SUITE 502  
 City: DENVER State: CO Zip: 80206
**Contact Information:**

Contact Name	Phone	Email	Comment
, Fulcrum		inspections@fulcrumeo.com	
Waldron, Emily		emily.waldron@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477016	OFF-LOCATION FLOWLINE	AC	06/22/2020		-	Production Line	AC
483714	OFF-LOCATION FLOWLINE	AC	01/25/2023		-	Surprise Unit 0680 S4 CTB	AC
483715	OFF-LOCATION FLOWLINE	AC	01/25/2023		-	Surprise Unit 0680 S4 CTB	AC
483716	OFF-LOCATION FLOWLINE	AC	01/25/2023		-	Surprise Unit 0680 S4 CTB	AC

**General Comment:****ECMC Inspection Report Summary**

On Wednesday 5/7/2025, I, Inspector Scott Ramsey, conducted a follow up inspection at Surprise CTB, at Location # 436676 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed a tank battery. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Dehy lacking bird protector
2. No access or evidence of calibration cards.
3. Stored equipment
4. Totes not contained.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meter calibration record not legible or conspicuously displayed at meter.		
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d. (2)	Date:	06/23/2025

Emergency Contact Number:			
Comment:	911/970-594-0477		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Totes not contained.		
Corrective Action:	Remove or provide proper containment	Date:	05/30/2025
Type	OTHER		
Comment:	Dehy lacking bird protector		
Corrective Action:	Eliminate possibility of wildlife to enter	Date:	05/30/2025
Type	STORAGE OF SUPL		
Comment:	Stored equipment		
Corrective Action:	Remove or put into use stored equipment	Date:	06/27/2025

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 17		
Comment:			
Corrective Action:		Date:	
Type: Other	# 18		
Comment:	Crypto mining equipment buildings		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	11 500 gallon engine oil tanks, 4 chemical totes, 6 chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Ancillary equipment	# 20		

Comment:	11 500 gallon engine oil tanks, 4 chemical totes, 6 chemical tanks in plastic containments			Date:	
Corrective Action:				Date:	
Type: Other	# 9				
Comment:	Gas powered generators			Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Dehydrator	# 1				
Comment:	Stored equipment			Date:	
Corrective Action:				Date:	
Type: VRU	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Compressor	# 1				
Comment:	Stored equipment			Date:	
Corrective Action:				Date:	
Type: Horizontal Separator	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Emission Control Device	# 2				
Comment:	Not running at time of inspection and are metered			Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	3		STEEL AST		
Comment:	Bullet tanks for striping gas unused/ stored equipment see housekeeping for C/A				
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	6	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	675 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	OTHER	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	675 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 477016 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 483714 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 483715 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 483716 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Gravel				
Gravel						
		Culverts				

Comment: Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801584	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047429">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047429</a>