

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2025

Submitted Date:

05/12/2025

Document Number:

707801577

FIELD INSPECTION FORM

Loc ID 439603 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Waldron, Emily		emily.waldron@state.co.us	
, Fulcrum		inspections@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444609	WELL	PR	02/01/2025	OW	057-06539	Gregory 0780 1-9H	PR
446904	WELL	AP	07/01/2022	LO	057-06568	Mutual 0780 5-8H	AP
446917	WELL	AP	07/01/2022	LO	057-06570	Mutual 0780 6-8H	AP
446918	WELL	AP	07/01/2022	LO	057-06571	Mutual 0780 8-8H	AP
446919	WELL	AP	07/01/2022	OW	057-06572	Mutual 0780 7-8H	AP
448055	WELL	PR	08/17/2022	OW	057-06586	Castle 0780 6-17H20	PR
448056	WELL	PR	01/01/2024	OW	057-06587	Castle 0780 5-17H20	PR
448057	WELL	PR	04/01/2024	OW	057-06588	Castle 0780 8-17H20	PR
448058	WELL	PR	11/01/2023	OW	057-06589	Castle 0780 7-17H20	PR
452319	WELL	PR	06/01/2024	OW	057-06603	Janet 0780 1-16H21	PR
452320	WELL	PR	06/01/2024	OW	057-06604	Janet 0780 2-16H21	PR
452321	WELL	SI	01/01/2025	OW	057-06605	Janet 0780 4-16H21	SI
452339	WELL	PR	04/01/2024	OW	057-06606	Janet 0780 3-16H21	PR

General Comment:

ECMC Inspection Report Summary

On Wednesday 5/7/2025, I, Inspector Scott Ramsey, conducted a follow up inspection at Gregory Pad, at Location # 439603 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed a tank battery. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Some random staining
2. No access or evidence of calibration cards.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Some random staining		
Corrective Action:	Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date:	06/20/2025
Type	OTHER		
Comment:	Gas meter calibration record not legible or conspicuously displayed at meter.		
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2)	Date:	06/23/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:			corrective date
Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Ancillary equipment	# 4		
Comment:	Gas powered generators		
Corrective Action:		Date:	
Bradenhead	# 9		
Comment:			
Corrective Action:		Date:	
Ancillary equipment	# 8		
Comment:	Crypto mining buildings		
Corrective Action:		Date:	

Type: Pump Jack	# 9	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	444609	Type:	WELL	API Number:	057-06539	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	446904	Type:	WELL	API Number:	057-06568	Status:	AP	Insp. Status:	AP
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	446917	Type:	WELL	API Number:	057-06570	Status:	AP	Insp. Status:	AP
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	446918	Type:	WELL	API Number:	057-06571	Status:	AP	Insp. Status:	AP
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	446919	Type:	WELL	API Number:	057-06572	Status:	AP	Insp. Status:	AP
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	448055	Type:	WELL	API Number:	057-06586	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	448056	Type:	WELL	API Number:	057-06587	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	448057	Type:	WELL	API Number:	057-06588	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	448058	Type:	WELL	API Number:	057-06589	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	452319	Type:	WELL	API Number:	057-06603	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452320 Type: WELL API Number: 057-06604 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452321 Type: WELL API Number: 057-06605 Status: SI Insp. Status: SI

Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____		
Comment:	Last produced 1/2025		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452339 Type: WELL API Number: 057-06606 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Culverts				
		Gravel				
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801581	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047430