

FORM INSP Rev X/20	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		Inspection Date: <u>05/07/2025</u> Submitted Date: <u>05/13/2025</u> Document Number: <u>707801579</u>
FIELD INSPECTION FORM			

Loc ID: 487288 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10805
 Name of Operator: FULCRUM ENERGY OPERATING LLC
 Address: 240 SAINT PAUL STREET SUITE 502
 City: DENVER State: CO Zip: 80206

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Fulcrum		inspections@fulcrumeo.com	
Waldron, Emily		emily.waldron@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487598	WELL	AP	08/19/2024		057-06637	Gregory 0780 6-4H9	AP
487599	WELL	PR	01/01/2025	OW	057-06638	PRU-Janet 0880 5-33H21	PR
487600	WELL	AP	08/19/2024		057-06639	Gregory 0780 4-4H9	AP
487601	WELL	PR	01/01/2025	OW	057-06640	PRU-Janet 0880 4-33H21	PR
487602	WELL	PR	01/01/2025	OW	057-06641	PRU-Janet 0880 3-33H21	PR
487603	WELL	AP	08/19/2024		057-06642	Gregory 0780 5-4H9	AP
487604	WELL	AP	08/19/2024		057-06643	Gregory 0780 7-4H9	AP
487605	WELL	PR	01/01/2025	OW	057-06644	PRU-Janet 0880 6-33H21	PR
487606	WELL	AP	08/19/2024		057-06645	PRU-Janet 0880 2-33H21	AP
487607	WELL	AP	08/19/2024		057-06646	PRU-Janet 0880 1-33H21	AP

General Comment:

[ECMC Inspection Report Summary](#)
 On Wednesday 5/7/2025, I, Inspector Scott Ramsey, conducted a follow up inspection at Janet 0780, at Location # 487288 in Jackson county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed a tank battery. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.
 During this inspection the following possible compliance issues were observed:

1. Stored equipment (active work on location)
2. No access or evidence of calibration cards.
3. Stock pile lacking proper BMP's (spoke with construction lead and was getting waddles delivered and he told me they were hauling the stock pile off soon)

Refer to photograph of observed compliance issue.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Entrance signage		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	1 500 gallon unknown contents.		
Corrective Action:	Provide proper labeling		Date: 05/30/2025

Emergency Contact Number:			
Comment:	911/970-594-0477		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Gas meter calibration record not legible or conspicuously displayed at meter.		
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).		Date: 06/27/2025
Type	STORAGE OF SUPL		
Comment:	Stored equipment (active work on location)		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	Line coolers		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 4		

Comment:	Triplex pumps for wells		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	4 chemical tanks and 1 500 gallon unknown contents.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	487598	Type:	WELL	API Number:	057-06637	Status:	AP	Insp. Status:	AP	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487599	Type:	WELL	API Number:	057-06638	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing									
Corrective Action:								Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487600	Type:	WELL	API Number:	057-06639	Status:	AP	Insp. Status:	AP	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487601	Type:	WELL	API Number:	057-06640	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing									
Corrective Action:								Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487602	Type:	WELL	API Number:	057-06641	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing									
Corrective Action:								Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487603	Type:	WELL	API Number:	057-06642	Status:	AP	Insp. Status:	AP	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487604	Type:	WELL	API Number:	057-06643	Status:	AP	Insp. Status:	AP	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487605	Type:	WELL	API Number:	057-06644	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing									
Corrective Action:								Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487606	Type:	WELL	API Number:	057-06645	Status:	AP	Insp. Status:	AP	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	487607	Type:	WELL	API Number:	057-06646	Status:	AP	Insp. Status:	AP	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Culverts				
Gravel						
Berms						

Comment: Stock pile lacking proper BMP's (spoke with construction lead and was getting waddles delivered and he told me they were hauling the stock pile off soon)

Corrective Action: Install proper BMP's

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801583	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047433