

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2025

Submitted Date:

05/13/2025

Document Number:

707603904

FIELD INSPECTION FORM

Loc ID 431214 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

22 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431212	WELL	SI	02/01/2024	OW	123-36479	Richter 34R-223	SI
431216	WELL	SI	01/01/2025	OW	123-36482	Richter 34M-203	SI
431218	WELL	SI	01/01/2025	OW	123-36484	Richter 34R-423	SI
431220	WELL	SI	04/01/2024	OW	123-36486	Richter 34M-423	SI
431222	WELL	SI	01/01/2025	OW	123-36487	RICHTER 34R-343	SI
431226	WELL	SI	09/01/2024	OW	123-36491	Richter 34R-403	SI
432425	WELL	SI	01/01/2025	OW	123-37100	Richter 34U-303	SI

General Comment:

This is a WELL inspection.
Well(s): 7: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID (431214).
(Well(s): 7: Shut-In | SI).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707603904 and/or Location ID #431214 for SI Well(s) info.
B.) Field Inspection Report doc. #707603906 and/or Location ID #431214 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellsite(s): 7 OOSLAT posted at well(s).		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Wellsite(s): 7: Paraffin Control. Placards.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Wellsite(s): 7 Iron panel.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Gas Lift injection meter(s), header(s). Iron pipe.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 9		corrective date
Comment:	Wellsite(s): 1: Methanol pump(s), tank(s) w/ drip containment. 1: Compressor for well pad. 7: Paraffin control pump(s), tank(s) w/ drip containment.		
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:	Wellsite(s): 7		
Corrective Action:			Date:

Type: Gas Meter Run	# 4		
Comment:	Wellsite(s): 4: Gas Lift Allocation; (Chevron). Calibration card(s) indicates calibration <= 1 year. Last calibration: 07/01/2024.		
Corrective Action:			Date:
Type: Other	# 7		
Comment:	Wellsite(s): 7 Gas Lift injection lines.		
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:	Wellsite(s): 7 Appears plumbed to surface.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.539190,-104.531620
Comment:	Centralized Battery serves 1 Location ID (431214). (Well(s): 7: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 04/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431220 Type: WELL API Number: 123-36486 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.
ECMC records last prod: 03/2024.
Locked-Out, Tagged-Out | LOTO.
OOSLAT posted at WH F-Line valve.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 04/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431222 Type: WELL API Number: 123-36487 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.
ECMC records last prod: 09/2024.
Locked-Out, Tagged-Out | LOTO.
OOSLAT posted at WH F-Line valve.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 04/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431226 Type: WELL API Number: 123-36491 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.
ECMC records last prod: 08/2024.
Locked-Out, Tagged-Out | LOTO.
OOSLAT posted at WH F-Line valve.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 10/03/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432425 Type: WELL API Number: 123-37100 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.
ECMC records last prod: 09/2024.
Locked-Out, Tagged-Out | LOTO.
OOSLAT posted at WH F-Line valve.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 04/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 05/08/2025 at approximately 14:12 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: Richter/34T-HZ Pad Location ID: 431214 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 7: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/13/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404202203	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047310
707603905	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047307