



Miller 2 & 7-7 Facility
Ⓢ 06-May-25 10:16:05 AM
ECMC Environmental Inspection


Former tank battery location. Orange construction fencing surrounds two open excavations at the former separator and produced water vault.



Approximate location of Spill ID 489966 (former produced water vault).



Approximate location of Spill ID 489966 (former produced water vault).



Approximate location of Spill ID 489977 (former separator location). Gray staining observed on excavation sidewalls.