

WGS84 $\pm 10\text{ft}$ 40.13307, -104.92146 $\pm 3\text{m}$ 1517 ± 11 °, T E103



Miller-62N67W 17SWSW
© 06-May-25 09:49:39 AM
ECMC Environmental Inspection

ECMC
Environmental
Field Inspection



An open excavation was observed on location. Debris has collected within the excavation. Concrete barriers were observed near the excavation, but did not surround the perimeter. No excavation fencing has been installed.

WGS84 $\pm 10\text{ft}$ 40.13307, -104.92120 $\wedge^m_{\pm 3\text{m}}$ 1516 $\triangle^{\circ, T}_{\pm 11}$ SE117



ECMC
Environmental
Field Inspection



Miller-62N67W 17SWSW
© 06-May-25 09:50:11 AM
ECMC Environmental Inspection



ECMC
Environmental
Field Inspection



Miller-62N67W 17SWSW
© 06-May-25 09:50:28 AM
ECMC Environmental Inspection

A monitoring well completed as a flush mount was observed adjacent to the excavation.



Miller-62N67W 17SW SW
© 06-May-25 09:50:51 AM
ECMC Environmental Inspection

ECMC
Environmental
Field Inspection



Gray staining is visible on the sidewalls of the excavation. A black wire extends along the excavation.



ECMC
Environmental
Field Inspection



Miller-62N67W 17SWSW
© 06-May-25 09:51:04 AM
ECMC Environmental Inspection

The former tank battery location is visible in the background.

WGS84 ±15ft 40.13309, -104.92121 1517 m ±4m °T ±11 NW340



ECMC
Environmental
Field Inspection 

Miller-62N67W 17SWSW
© 06-May-25 09:51:25 AM
ECMC Environmental Inspection

Multiple monitoring wells completed as flush mounts were observed on the location.