

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2025

Submitted Date:

05/13/2025

Document Number:

717100190

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Rollins, Grace 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489966	SPILL OR RELEASE	CL			-	Miller 2 & 7-7 Facility	EI
489977	SPILL OR RELEASE	AC			-	Miller 2-7 Flowline	EI

General Comment:

ECMC Environmental Field Inspection Report Summary

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 489966

Spill Name: Miller 2 & 7-7 Facility

Remediation Project #: 37995

Facility ID: 469711

Reported Date of Discovery: 04/24/2025

AND

Spill ID: 489977

Spill Name: Miller 2-7 Flowline

Remediation Project #: 37989

Wellhead API #: 05-123-23479

Reported Date of Discovery: 04/22/2025

Date of Inspection: 05/06/2025

Spill is located within or adjacent to:

- Crop land (immediately adjacent, north, south, and east)
- Livestock (~150 ft west)
- Residential building unit (~410 ft southwest)
- Riverine Wetlands and Irrigation Canal (~375 ft northwest)
- 100-year floodplain (~500 ft northwest)
- Bald Eagle Roost Site High Priority Habitat (~200 ft southwest)

Current site status:

- Excavations remain open at the locations of Spill ID 489966 (former produced water vault) and Spill ID 489977 (former flowline connection to separator).
- No groundwater was observed in the open excavations.
- No environmental impacts were visible in situ at the former produced water vault excavation.
- Gray staining was visible on the sidewalls of the former separator excavation.
- Orange construction fencing surrounds the excavations.

See attached corrective actions. A Supplemental Form 27 is required for Remediation Project # 37995 and Remediation Project # 37989.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type			
Comment:	Orange construction fencing surrounds the excavations.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project # 37995 was created for decommissioning of the Miller 2 & 7-7 Facility. Remediation Project # 37989 was created for the plugging and abandonment of the Miller 2-7 wellhead and decommissioning of the associated flowline. No groundwater was observed in the open excavations. No environmental impacts were visible in situ at the former produced water vault excavation. Gray staining was visible on the sidewalls of the former separator excavation. Quarterly reporting is required under Remediation Project # 37995; the last Form 27 for this project was submitted 01/29/2025 (Document Number 404073402). Quarterly reporting is required under Remediation Project # 37989; the last Form 27 for this project was submitted 01/29/2025 (Document Number 404073390). The most recent Form 19 was submitted on 04/24/2025; the Operator's request for closure of Spill ID 489977 was removed at the time of approval by ECMC on 05/01/2025. A Form 19 – Supplemental Report which requests closure of Spill ID 489977 is due by 07/21/2025.

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project # 37995 and Remediation Project # 37989.

Date: 05/27/2025

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100191	ECMC Photo Log - Miller 2 & 7-7 Facility & 2-7 Flowline - 05.06.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047744