

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC M17OU PAD

Location ID: 311752

Date: 05/8/2025



Photo # 7272 Entrance to location




Photo # 7307 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC M17OU PAD

Location ID: 311752

Date: 05/8/2025



Photo # 7275 Location



Photo # 7282 Location

Inspection/Audit Photos
Location: QB ENERGY OPERATING LLC M17OU PAD
Location ID: 311752
Date: 05/8/2025



Photo # 7298 Location



Photo # 7305 Location - 1 unused flowline at tank battery lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC M17OU PAD

Location ID: 311752

Date: 05/8/2025



Photo # 7319 SE corner of location



Photo # 7320 SW corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC M17OU PAD

Location ID: 311752

Date: 05/8/2025



Photo # 7321 NW corner of location



Photo # 7324 NE corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC M170U PAD

Location ID: 311752

Date: 05/8/2025



Photo # 7293 Multiple unused flowlines at separators lack lockout tagout (OOSLAT)



Photo # 7301 Methanol tank lacks required information. Additionally capacity is incorrect.

Inspection/Audit Photos
Location: QB ENERGY OPERATING LLC PAD
Location ID: 311752
Date: 05/8/2025



Photo # 7315 Open ended load line



Photo # 7314 One condensate tank is rusting in some areas, paint is inadequate.