

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2025

Submitted Date:

05/07/2025

Document Number:

713302034**FIELD INSPECTION FORM**Loc ID 311331 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>
Revas, Robbie		robbie.revas@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242086	WELL	SI	11/01/2021	GW	123-09877	HLADKY-O'GORMAN 4	SI

**General Comment:**[well site inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	missing		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/11/2025

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	open excavation, caution fence down		
Corrective Action:	repair protection equipment. Comply with Rule 608a	Date:	05/14/2025
Type	OTHER		
Comment:	electric disconnect, metal panels		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 242086 Type: WELL API Number: 123-09877 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Form 6 on file, well P&A 2-17-2025, doc 404092808  
Form 27 on file, Remediation 11-14-2024, doc 403922492

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents conducted on-site inspection, Location: Hladky O Gorman 4 Operator: KPK API#: 123-09877 County: Weld While there, I observed remediation project well site, During this inspection the following possible compliance issues were observed:</p> <p>Sign, Rule 605d, corrective action date 6-11-2025, photos 1 &amp; 2 Excavation safety fence, Rule 608a, corrective action date 5-14-2025, photos 1 &amp; 2</p> <p>Weather conditions: overcast/cloudy</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	05/07/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404194629	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7039540">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7039540</a>
713302035	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7039534">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7039534</a>