

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/23/2025

Submitted Date:

05/07/2025

Document Number:

718800237**FIELD INSPECTION FORM**Loc ID 336169 Inspector Name: Mitchem, Katelyn On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------|
| , | | ECMCInspections@oxy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|--------------------------------|-------------|
| 258607 | WELL | PA | 06/07/2022 | GW | 123-20179 | HSR ATLER FEDERAL 9-5A | RI |
| 259403 | WELL | PA | 10/04/2016 | GW | 123-20321 | HSR-ATLER 10-5 | RI |
| 336169 | LOCATION | CL | | | - | HSR ALTER FEDERAL-61N66W 5NESE | RI |

General Comment:

This is a Final Reclamation Inspection for a PA multi-well location, Location ID# 336169, and its associated tank battery. The last well was plugged and abandoned on 06/07/2022.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

| Type | Area | Volume | | |
|--|------|--------|--|--|
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Equipment:

| Type: | # | | corrective date |
|--------------------|---|---|-----------------|
| Comment: | | No visual evidence of oil and gas equipment at the location. Refer to the attached inspection photos. | |
| Corrective Action: | | Date: | |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Environmental | | | |
|--|------------------------------|-------------------------------|-------|
| Spills/Releases: | | | |
| Type of Spill: _____ | | Estimated Spill Volume: _____ | |
| Comment: <div>ECMC confirms that all remediation projects are approved and closed.</div> | | | |
| Corrective Action: _____ | | Date: _____ | |
| Reportable: _____ | GPS: Lat _____ | Long _____ | |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | | |
| Water Well Complaint: | | | |
| | | Lat | Long |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : | _____ |
| Field Parameters: | | | |
| | | | |
| Sample Location: _____ | | Comment: _____ | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: **This location does not meet reclamation regulations as the access road has not been reclaimed and there is insufficient vegetative cover. Comply with 1004 rules to establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels.**

Corrective Action: **Comply with Rule 1004 reclamation standards and reclaim the access road.** Date _____

Overall Final Reclamation **Fail** Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|-------------------|
| | | | | | | |
| Comment: <div>At the time of this inspection, no stormwater erosion issues were observed at location or along the access road.</div> | | | | | | |
| Corrective Action: <div></div> | | | | | | Date: <div></div> |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT | | | | | | |

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404194723 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7039680 |
| 718800238 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7039640 |