

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2025

Submitted Date:

05/08/2025

Document Number:

718100507

FIELD INSPECTION FORMLoc ID 324475 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 999 18TH STREET SUITE 1755N

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
,		geops@oxbow.com	Inspection mail box
Chamard, Megan		megan.chamard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278793	WELL	SI	12/01/2018	GW	051-06064	HOTCHKISS FEDERAL 12-89 17-13	RI
324475	LOCATION	AC			-	DGU Federal 1289 17-13 Pad	RI
436660	WELL	DG	09/01/2019	LO	051-06127	DGU Federal 1289 17-13 CS2	RI

General Comment:

On 5/6/2025, Western Reclamation Work Lead Trujillo conducted an interim reclamation inspection at Gunnison Energy's DGU Federal 1289/17-13 Pad location in Gunnison County, Colorado.

This inspection is a follow-up to #696206398 to document compliance with the following corrective actions:

- Stockpile protections
- Excavations missing required fencing
- Final Reclamation requirements
- "As Drilled" coordinate requirements

It was observed in this inspection that the corrective actions related to stockpile protections and fencing requirements has been resolved; corrective actions related to final reclamation requirements and "As Drilled" coordinate requirements remain outstanding.

Refer to the "Location" and "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	Previous inspection observed excavations throughout the Location were missing required fencing. Inspection required Operator to comply with Rule 913.b. Excavations have since been backfilled; CA is no longer applicable however it is noted that no Resolution pursuant to Rule 210.b was submitted showing corrective actions had been taken.		
Corrective Action:		Date:	

Equipment:

Type:	#		corrective date
Comment:	Inspection #696206398 documented that the coordinates for well API 05-051-06064, including the "as drilled" coordinates, are incorrect. Inspection required Operator to submit corrected coordinates for wells on the Location, and to comply with Rule 216 for GPS/PDOP requirements. Unable to find any record or submission of forms to correct the "as drilled" coordinates; scout card records remain inaccurate. This CA has not been addressed and remains applicable. It is also noted that the coordinates provided within Form 6(s) 403899875 are the incorrect Lat/Long that was measured 4/25/2007. Pursuant to Rule 206.b, records are required to be accurate. Form 6(s) remains in process at time of inspection. Including area Engineer for notification.		
Corrective Action:	Submit correct coordinates for wells on the Location. Comply with Rule 216 for GPS/PDOP requirements.		Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	278793	Type:	WELL	API Number:	051-06064	Status:	SI	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	324475	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	436660	Type:	WELL	API Number:	051-06127	Status:	DG	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Pursuant to Rule 1004.a, upon the plugging and abandonment of a well, all debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.

Previous inspection observed that pipe equipment on the northwest end of the Location has not been removed. Pursuant to Form 6(s) 403899875, the only PR well on the Location (051-06064) was P&Ad 6/29/2024- all surface equipment was required to be removed by 9/29/2024. Inspection required Operator to comply with Rule 1004.a, and remove all surface equipment from the Location.

It was observed in this inspection that the pipe equipment has not been removed. This CA has not been addressed and remains applicable.

Corrective Action: **Comply with Rule 1004.a and removal all surface equipment from the Location.**

Date _____

Overall Final Reclamation ☐

Well Release on Active Location ☐

Multi-Well Location ☐

ECMC Comments

Comment	User	Date
Remediation Proj. #36474 for Facility Closure (#404053086) in process at time of inspection. Final reclamation pursuant to 1004 Rules required at the Location and access road upon closure of the remediation project.	trujilloam	05/08/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404196714	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7041471
718100508	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7041467