

Inspection Photos

May 8th, 2025

Operator: Maralex Resources - 53255

Location ID: 333984

Inspection Document #: 714002159

La Plata County, CO

Township: NWSW 14 33W 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. View of the well pad taken from the access point facing center.



Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID:333984



May 8, 2025
279° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Weedy debris encroaching on equipment.

API #: 067-09621, 09623

Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID:333984



Photo 3. Stained soils at lube tank secondary contaminants.

Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID:333984



May 8, 2025
229° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Unused pumpjack panel stored on location.

API #: 067-09621, 09623

May 8, 2025
64° NE



Photo 5. Patch of Musk Thistle observed at pumpjack.

Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID:333984

May 8, 2025
104° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Tanks on location are missing labels.

API #: 067-09621, 09623