

Inspection Photos  
Location Name: Franson 34-28 4N47W  
API Number: 125-09698



1. Lease sign at well location.



2. View of wellhead.

**Inspection Photos**  
**Location Name: Franson 34-28 4N47W**  
**API Number: 125-09698**



**3. View where previous FIR had noted release from check valve. CA completed with no fluid release at check valve.**



**4. Open ended line noted in previous FIR. CA completed and plug installed on tubing line.**