

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2025

Submitted Date:

05/15/2025

Document Number:

717300338

FIELD INSPECTION FORM

Loc ID 305090 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274043	WELL	TA	02/26/2019	GW	123-22431	PARAGON FARMS 42-25	PA
319502	LOCATION	AC			-	BADDING USX W 25-07D	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 274043 Type: WELL API Number: 123-22431 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 319502 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Paragon Farms 42-25); ECMC form 42 notice of start of plugging operations doc #403851497 received on 07/11/2024. Wellhead OLF has been removed; bellhole excavations observed at flowline pipe removal pull points between WH & battery (backfilled). The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #403985300 received 11/06/2024 (OL facility FL's removed). No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	05/15/2025
As outlined on ECMC form 19 spill report Doc #404193097 received on 05/13/2025: While conducting facility decommissioning activities at the Paragon Farms 42-25 Facility, historically impacted soil was discovered beneath the former separator. The volume of the release is unknown. Site infrastructure has been removed and will not be replaced.	maclarej	05/15/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300339	Excavation and signage at facility; Decom	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051316
717300340	PA well; BH excavations backfilled	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051317
717300341	Facility/ battery decommissioned; view W	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051318