

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2025

Submitted Date:

05/15/2025

Document Number:

707603908

**FIELD INSPECTION FORM**Loc ID 434745 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Steinke, Ivan		isteinke@civiresources.com	Regulatory Manager; DJ Basin
,		Inspections@civiresources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434745	LOCATION	AC			-	State North Platte O-26 Pad	AO

**General Comment:**

This is a LOCATION inspection.

Well(s): 13: Producing | PR.

Battery: Active.

Centralized Battery serves 12 Location IDs

(432636, 434745, 429060, 310744, 433511, 454278, 432395, 441915, 434121, 332135, 445363, 470863).

(Well(s): 85: Producing | PR; 13: Shut-In | SI).

Centralized Battery serves 1 Tank Battery Facility ID

(481579).

**\*\*This is a FOLLOW\_UP INSPECTION.**

FWP to FIELD INSPECTION REPORT DOC #707603671 dated 01/29/2025.

Corrective Action(s) from prior inspection report remain UNADDRESSED and applicable.

Corrective Action(s) from prior inspection report date: 03/21/2025. FAILED to MITIGATE.

NEW CORRECTIVE ACTION DATE: 05/29/2025. (2-Weeks).

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location signage.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unnecessary equipment at Location site. See North side of Location site. Unnecessary equipment includes: Frac tank w/ spill pad. Refer to Rule 606 for guidance.		
Corrective Action:	*Remove unnecessary equipment from Location site. Comply with Rule 606. Prior Corrective Action date: 03/21/2025. NEW Corrective Action date: 05/29/2025. See photo(s) #1, 2, 3, 6, 7. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date: 05/29/2025

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	434745	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 05/09/2025 at approximately 13:11 hrs. I, Bret Evins, conducted an onsite inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: State North Platte/O-26 Pad  Location ID: 434745  Well Name(s) &amp; API:  Reference:  **FIR document #707603615, dated 01/29/2025.  Location County: Weld County, Colorado  Weather: Partly Sunny, dry.</p> <p>While there, I observed:  Well(s): 13: Producing   PR.  Battery: Active.</p> <p><b>**CORRECTIVE ACTION(s) COMMENT:</b>  During this inspection the following possible compliance issue(s) were observed:  1.) Unnecessary equipment at Location site.  See North side of Location site.  Unnecessary equipment includes:  Frac tank w/ spill pad.  Refer to Rule 606 for guidance.  *Remove unnecessary equipment from Location site.  Comply with Rule 606.  Prior Corrective Action date: 03/21/2025.  NEW Corrective Action date: 05/29/2025.  See photo(s) #1, 2, 3, 6, 7.  *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/15/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603909	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051988">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051988</a>