

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2025

Submitted Date:

05/09/2025

Document Number:

718100518

**FIELD INSPECTION FORM**Loc ID 490082 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 999 18TH STREET SUITE 1755N

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		geops@oxbow.com	<a href="#">Inspection mail box</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
490082	LOCATION	AC	05/07/2025		-	Gunnison Tank 11S90W	RI

**General Comment:**

On 5/6/2025, Western Reclamation Work Lead Trujillo conducted an inspection at Gunnison Energy LLC's Gunnison Tank 11S90W facility Location in Gunnison County, Colorado.

The following compliance issues were observed during this inspection:

- Good Housekeeping
- Weeds
- Signage requirements

Refer to the Location sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Tank battery signage does not comport with Rule 605 requirements, and does not include information such as the well names and API number associated with the tank battery., and the legal location of the wells.		
Corrective Action:	Comply with Rule 605.e.	Date:	06/09/2025
Type	TANK LABELS/PLACARDS		
Comment:	Signage/labeling at tank does not comport with 605 requirements.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 970-874-7697

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type			
Comment:	Various trash, debris and unused equipment observed throughout the Location		
Corrective Action:	Comply with 606 rules.	Date:	05/16/2025
Type	WEEDS		
Comment:	Undesirable and Noxious Plant Species (Common mullein and Musk thistle rosettes) observed established throughout the Location		
Corrective Action:	Comply with Rule 606.c. Oil and Gas Locations will be kept free of all Undesirable Plant Species.	Date:	05/24/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Sheep fencing		
Corrective Action:		Date:	

**Equipment:**

Type:	#		corrective date
Comment:	Riser on Location appears to be open to atmosphere, and missing cap or plug; hosing has been disconnected		
Corrective Action:	Install cap/plug at open pipe equipment.		Date: 05/16/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:	Containment berm damaged on the east end of the facility. It is not clear at time of inspection if BMP is in proper functioning condition. Maintenance advised.			
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

