

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2025

Submitted Date:

05/09/2025

Document Number:

696307549

**FIELD INSPECTION FORM**Loc ID 436427 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD State: CO Zip: 80111

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Parrish, Melissa	970-397-3896	mparrish@fundareresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436423	WELL	PR	10/01/2017	OW	123-39116	Razor 25B-2550	PR
436425	WELL	PR	10/01/2017	OW	123-39118	Razor 25B-2551	PR
436426	WELL	PR	10/10/2014	OW	123-39119	Razor 25B-2549	PR
438493	WELL	PR	10/01/2017	OW	123-40021	RAZOR 25B-2450	PR
438496	WELL	PR	12/01/2017	OW	123-40023	RAZOR 25B-2449	PR
438497	WELL	PR	10/01/2017	OW	123-40024	RAZOR 25B-2451	PR

**General Comment:**

This is a Well PAD and Production Facility Field Compliance Audit

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Compressor Drain Vault is missing Signage; see photos		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		

Comment:		Appear to be plumbed to surface		Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 10				
Comment:				Date:	
Corrective Action:				Date:	
Type: Vertical Separator	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 6				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Separator	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Vertical Heater Treater	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Compressor	# 1				
Comment:				Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:		Shares berm with the Crude Oil Tanks			
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLS	STEEL AST		40.816740,-103.811740
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Field Flare	
Comment:	Candlestick Flare does not meet ECMC requirements for Enclosed Combustion. Provide Documentation that shows 98% design destruction efficiency	
Corrective Action:	Comply with Rule 903.(5).	Date: 06/06/2025

**Inspected Facilities**

Facility ID: 436423 Type: WELL API Number: 123-39116 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436425 Type: WELL API Number: 123-39118 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436426 Type: WELL API Number: 123-39119 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438493 Type: WELL API Number: 123-40021 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438496 Type: WELL API Number: 123-40023 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438497 Type: WELL API Number: 123-40024 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404197962	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042938">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042938</a>
696307550	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042930">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042930</a>