

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2025

Submitted Date:

05/09/2025

Document Number:

696307553**FIELD INSPECTION FORM**Loc ID 436724 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10773Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 950City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Parrish, Melissa	970-397-3896	mparrish@fundareresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436730	WELL	PR	11/19/2014	OW	123-39240	Horsetail 33M-2804	PR

**General Comment:**This is a Follow-Up to FIR 696307330 dated 03.03.2025

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	400 BBLS	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

**Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: South end of Tank berm is compromised - Corrective Action Date of 04.18.2025 has past, Original Corrective Action Date remains the same *East Center part of Berm was discovered to be compromised as well at the time of this Field Audit See Photos				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 04/18/2025

**Venting:**Yes/No Comment: Corrective Action: Date: **Flaring:**

Type	
Comment: <input type="text"/>	
Corrective Action: <input type="text"/>	Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 436730 Type: WELL API Number: 123-39240 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment

User

Date

Routine Follow-Up Field Compliance Audit. South end of Tank berm is compromised - Corrective Action Date of 04.18.2025 has past, Original Corrective Action Date remains the same. \*East Center part of Berm was discovered to be compromised as well at the time of this Field Audit. See Photos. Repair or install berms or other secondary containment devices per Rule 603.o.

petrie

05/09/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404197968	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042940">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042940</a>
696307554	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042933">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042933</a>