

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2025

Submitted Date:

05/09/2025

Document Number:

716300944

## FIELD INSPECTION FORM

Loc ID 322219 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 74975

Name of Operator: SAN MARCO PETROLEUM INC

Address: 240 MILWAUKEE ST STE 200

City: DENVER State: CO Zip: 80206-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sheridan, John	303-905-5919	jsheridanvc@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209942	WELL	PR	03/01/2021	OW	043-06020	ADAMIC 1-20	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 6: Mechanical issue well head leaking around tubing nut see video.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.. THIS IS THE SECOND NOTICE, IMMEDIATE ACTION IS REQUIRED.		Date:
Type	WEEDS		
Comment:	PHOTO 5: WEEDS INSIDE TANK BATTERY BERMS.		
Corrective Action:	REMOVE WEEDS INCLUDING ROOT STRUCTURES ON AND INSIDE TANK BATTERY BERMS PER RULE 606.		Date: <u>05/21/2025</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Ancillary equipment	# 1		
Comment:	ELECTRIC METER AND EQUIPMENT		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE (BRADENHEAD IS LEAKING SEE HOUSEKEEPING FOR CORRECTIVE ACTION)		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	ELECTRIC DRIVE		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST		38.378851,-105.128139	
Comment:	TANKS HAVE NO PRESSURE PRESSURE RELIEF VALVE INSTALLED AND GAS IS LEAKING THROUGHT GUAGE HATCH ON BOTH TANKS. SEE ATTACHED FLIRR VIDEO.					
Corrective Action:	Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9).				Date:	<u>05/12/2025</u>

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	210 BBL				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Inadequate	
Comment:					
Corrective Action:					Date: <div></div>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <div></div>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <div></div>

Inspected Facilities									
Facility ID:	209942	Type:	WELL	API Number:	043-06020	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:	12/04/2024		Annual Brhd Completed?	No					
Last Brhd Test Results	Initial Surf Csg Pressure:		0		Fluid Type: NONE				
	End Surf Csg Pressure:		0						
Comment:	NOTE: BRADENHEAD IS LEAKING SO A PROPER BRADENHEAD TEST CANNOT BE PERFORMED. SEE HOUSEKEEPING FOR CORRECTIVE ACTION.							06/09/2025	
Corrective Action:	7 DAYS AFTER REPAIRING BRADENHEAD LEAK PERFORM A PROPER BRADENHEAD TEST AND SUBMIT REPORT.							Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #707901288, CA'S HAVE NOT BEEN ADDRESSED, IMMEDIATE ACTION IS REQUIRED. THIS IS A SECOND NOTICE ON BRADENHEAD LEAK.	beardslt	05/09/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404197696	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042584">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042584</a>
716300945	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042575">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042575</a>
716300946	BRHD LEAK FLIRR VIDEO	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042577">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042577</a>
716300947	TANK BATTERY FLIRR VIDEO	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042578">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042578</a>