

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2025

Submitted Date:

05/16/2025

Document Number:

693808665

FIELD INSPECTION FORM

Loc ID 316844 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10841
Name of Operator: AMERICAN HELIUM LLC
Address: 23501 CINCO RANCH BLVD, B244
City: KATY State: TX Zip: 77494

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Joyner, Ryan	970.385.6289	rjoyner@blm.gov	Tres Rios
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271807	WELL	TA	01/01/2017	GW	113-06143	FOSSIL FEDERAL 1-24	TA

General Comment:

ECMC staff performed a routine field inspection on 5/12/2025.
Issues were found requiring corrective action. See inspection text and photos for details.
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
Lease Road:			
Type	Main		
comment:			
Corrective ActionL		Date:	
Type	Access		
comment:			
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign on flowline barricade		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	435-631-2239		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	pipe barricade at off location flowline riser.		
Corrective Action:		Date:	
Equipment:			
			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	Various sizes		
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 271807 Type: WELL API Number: 113-06143 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 09/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: 06/16/2025

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693808668	Inspection photos 5/12/2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052826