

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2025

Submitted Date:

05/16/2025

Document Number:

693808667**FIELD INSPECTION FORM**Loc ID 333072 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10841Name of Operator: AMERICAN HELIUM LLCAddress: 23501 CINCO RANCH BLVD, B244City: KATY State: TX Zip: 77494**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Joyner, Ryan	970.385.6289	rjoyner@blm.gov	<a href="#">Tres Rios</a>
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	<a href="#">Field Inspector</a>
Lapham, Ken	979-877-4951	klapham@americanhelium.us	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89428	WELL	SI	12/01/2022	GW	113-06069	FOSSIL FEDERAL 5	SI
266298	WELL	SI	06/01/2022	GW	113-06120	FOSSIL FEDERAL 5-19	SI

**General Comment:**

ECMC staff performed a routine field inspection on 5/12/2025.  
 Issues were found requiring corrective action. See inspection text and photos for details.  
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location				
<b>Lease Road:</b>				
Type	Main			
comment:				
Corrective Action	L			Date:
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Signs on wellheads and Meter housings			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	435-631-2239			
Corrective Action:				Date:
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	No safety fence or netting at excavation on NE corner of pad			
Corrective Action:	Install safety fence or netting.			Date: 06/16/2025
Type	UNUSED EQUIPMENT			
Comment:	Unused tank ladder section			
Corrective Action:	Comply with Rule 606			Date: 06/16/2025
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Panel fence			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Bird Protectors	# 3			corrective date
Comment:				

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	Separators disconnected and blind flanged by BLM		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	Various sizes		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	200 BBLS	HEATED STEEL AST		38.063068,-108.682230
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	Fresh water
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		38.063283,-108.682691
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 89428 Type: WELL API Number: 113-06069 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Tubing valve locked out by BLM.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 05/08/2025 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 266298 Type: WELL API Number: 113-06120 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Tubing valve locked out by BLM.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 05/07/2025 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 301 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693808669	Inspection photos 5/12/2025	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052827">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7052827</a>