

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2025

Submitted Date:

05/19/2025

Document Number:

707603918

FIELD INSPECTION FORM

Loc ID 415988 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_ecmc_engineering@state.co.us	
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416118	WELL	TA	06/26/2018	OW	123-31283	70 RANCH USX BB 35-01P	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Cementing; cut-csg; base plug.
Battery: Abandoned.
Abandoned Battery SE corner GPS coordinates: 40.359019 / -104.397735
Well GPS coordinates: 40.361020 / -104.396280

****This is a CORRECTED FIR & Supersedes Document #707603914 dated 05/09/2025.**

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 416118 Type: WELL API Number: 123-31283 Status: TA Insp. Status: PA

Cement

Cement Contractor

Contractor Name: JMR Services, LLC Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2154'-1852' Cement Volume (sx): 120 sxs

Good Return During Job: _____ Cement Type: Class "G" Neat 15.8#

Comment: 2025/05/09:
 Plugging Operations: Cementing; cut-csg; base plug.
 2025/05/09: JSA attached as photo to this report.

Workover Contractor: JMR Services, LLC Rig #4.
 Cement Contractor: JMR Services, LLC.

ISITP-0 PSI, ISICP-0 PSI, ISISCP-2 PSI, PRES/TEST EXISTING CIBP TO 1500 PSI FOR 15 MIN, HELD GOOD, N/D TOP FLANGE, N/U BOP AND TBG EQUIPMENT, POOH STANDING BACK 66 JTS AND L/D REST OF TBG, MIRU JMR WL, RIH AND JET CUT CSG @2154', ESTABLISH CIRCULATION AND CONDITION HOLE, N/D TBG EQUIPMENT, BOP AND TBG HEAD, UN LAND CSG, N/U SPOOL, BOP AND 4 1/2 EQUIPMENT, SPOT 120 SKS OF NEAT G CMT AT 15.8 PPG AND 1.15 Y W/2%CC FROM 2154' TO 1852', POOH AND L/D 50 JTS OF 4 1/2 CSG, SECURE WELL, SDFN.

Corrective Action: _____ Date: _____

Workover

Comment: 2025/05/09:
 Plugging Operations: Cementing; cut-csg; base plug.
 2025/05/09: JSA attached as photo to this report.

Workover Contractor: JMR Services, LLC Rig #4.
 Cement Contractor: JMR Services, LLC.

Reference:
 Form 6N on file. Notice of Intent to Abandon date: 04/03/2025. Approved.
 Form 42 on file. Notice of MIRU. Start Date: 05/12/2025. Approved.
 Form 42 on file. Notice of Plugging Operations. Start Date: 05/12/2025. Approved.
 Email on file. Notice of Plugging Operations. Start Date: 05/08/2025. See E-RemindMe.
 Form 17 Brhd test on file. Date: 05/08/2025. Approved.
 Form 27 on file. Remediation Workplan. Date: 04/18/2025. Approval Pending.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 05/09/2025 at approximately 13:51 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: 70 Ranch USX BB/35-01P Location ID: 415988 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing; cut-csg; base plug. Battery: Abandoned. Abandoned Battery SE corner GPS coordinates: 40.359019 / -104.397735 Well GPS coordinates: 40.361020 / -104.396280</p> <p>Routine inspection.</p> <p>**This is a CORRECTED FIR & Supersedes Document #707603914 dated 05/09/2025.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/19/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603919	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7055589