

**Inspection Photos**  
**Location Name: Carl Miller Flowline**  
**Spill ID: 490177**



**Spill from a distance**

**Inspection Photos**  
**Location Name: Carl Miller Flowline**  
**Spill ID: 490177**



**Spill up close**

**Inspection Photos**  
**Location Name: Carl Miller Flowline**  
**Spill ID: 490177**



**Spill with visible dark staining and hydrocarbon odor**



Inspection Photos  
Location Name: Carl Miller Flowline  
Spill ID: 490177



Spill with visible dark staining and hydrocarbon odor


Inspection Photos  
Location Name: Carl Miller Flowline  
Spill ID: 490177



Spill with visible dark staining and hydrocarbon odor



**Inspection Photos**  
**Location Name: Carl Miller Flowline**  
**Spill ID: 490177**



**Tire tracks and flags**

