

**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Fencing around the excavation has fallen**



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Fencing around the excavation has fallen**



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Fencing around the excavation has fallen**



**Stockpile**





**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Stockpile**



**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Rips and tears in the liner under the stockpile**





**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Rips and tears in the liner under the stockpile**



**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Rips and tears in the liner under the stockpile**





**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Rips and tears in the liner under the stockpile**



**Contaminated soil has overflowed off the line and onto the ground surface**





**Inspection Photos**  
**Location Name: Lanson Farms 15 Flowline**  
**Spill ID: 487675**



**Contaminated soil has overflowed off the line and onto the ground surface**



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources