


TEP  
Daley 1  
Location ID: 323891




Location




Location



TEP  
Daley 1  
Location ID: 323891



Location



Location





TEP  
Daley 1  
Location ID: 323891



Location



Debris inside tank battery fence



TEP  
Daley 1  
Location ID: 323891



**Recent inspection photo of culvert lacks maintained**



**Previous inspection photo of culvert**



TEP  
Daley 1  
Location ID: 323891



**Recent inspection photo of culvert lacks maintained**



**Previous inspection photo of culvert**



TEP  
Daley 1  
Location ID: 323891



Recent inspection photo of culvert lacks maintained



Recent inspection photo of culvert lacks maintained