

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2025

Submitted Date:

05/09/2025

Document Number:

719000035

FIELD INSPECTION FORM

Loc ID: 306755 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments
1 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263013	WELL	SI	01/01/2025	CBM	067-08704	TINKER FEDERAL 2	SI

General Comment:

Inspection Report Summary
On 05/07/25 | Inspector Charles Garcia conducted an on-site inspection.
Location: Tinker Federal 2
Operator: Simcoe LLC
API#: 067-08704
County: LaPlata
Well shut in status and appears to be in reclamation Process

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance of location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		Date:
Corrective Action:			
Good Housekeeping:			
Type	OTHER		
Comment:	All 4 sides of location have signs seeded area KEEP OUT		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Combustible/potentially combustible within 25' of wellheads, tanks and separators Rule 610.k		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Cattel panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Catel panles		
Corrective Action:			Date:
Type	LOCATION		
Comment:	4 ft barbwire		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run # 1			corrective date
Comment:	Last Calibration 02/11/25		
Corrective Action:			Date:
Type: Flow Line # 1			
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Eletrical Panels		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Well Head		
Corrective Action:			Date:
Type: Deadman # & Marked	# 0		
Comment:	Dead men have been removed		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		
Comment:	Partially buried 21 BBL tank				
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:	It appears, paint peeled, visible corrosion/bare metal "Inspect, maintain/paint tank per Rule 609.b"	
Corrective Action:	"Inspect, maintain/paint tank per Rule 609.b"	Date: 07/09/2025

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 263013 Type: WELL API Number: 067-08704 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Satisfactory last reported production Dec 2024",

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000041	Location Pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7056665