

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1669 From entrance to location




Photo # 1670 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1671 Location



Photo # 1672 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1673 Location



Photo # 1674 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1675 Location



Photo # 1676 Debris

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1677 Unused flowlines do not comply with CECMC rules



Photo # 1678 Unused flowlines do not comply with CECMC rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1679 Holes in secondary containment liner/liner needs maintenance



Photo # 1680 Holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1681 Hole in secondary containment liner/liner needs maintenance



Photo # 1682 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1683 Hole in secondary containment liner/liner needs maintenance



Photo # 1684 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1685 Hole in secondary containment liner/liner needs maintenance



Photo # 1686 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 1-16C (P1W) Pad

Location #: 334612



Photo # 1687 Hole in secondary containment liner/liner needs maintenance



Photo # 1688 Hole in secondary containment liner/liner needs maintenance