

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2025

Submitted Date:

05/13/2025

Document Number:

708303804

**FIELD INSPECTION FORM**
 Loc ID 425899 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smelser, Wayne		wayne.smelser@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425882	WELL	PR	08/28/2012	GW	045-21098	Dixon Federal 42A-22-692	PR
425883	WELL	PR	08/28/2012	GW	045-21099	Dixon Federal 42B-22-692	PR
425884	WELL	PR	09/26/2012	GW	045-21100	Dixon Federal 41D-22-692	PR
425886	WELL	PR	08/28/2012	GW	045-21101	Dixon Federal 42C-22-692	PR
425888	WELL	PR	08/28/2012	GW	045-21103	Dixon Federal 12A-23-692	PR
425890	WELL	PR	09/24/2012	GW	045-21104	Dixon Federal 11B-23-692	PR
425892	WELL	PR	09/17/2012	GW	045-21105	Dixon Federal 42D-22-692	PR
425894	WELL	PR	10/09/2012	GW	045-21107	Dixon Federal 11A-23-692	PR
425895	WELL	PR	09/17/2012	GW	045-21108	Dixon Federal 41A-22-692	PR
425897	WELL	PR	09/17/2012	GW	045-21109	Dixon Federal 41C-22-692	PR
425898	WELL	PR	12/03/2012	GW	045-21110	Dixon Federal 11C-23-692	PR
425900	WELL	PR	10/28/2012	GW	045-21111	Dixon Federal 41B-22-692	PR
425902	WELL	PR	09/24/2012	GW	045-21112	Dixon Federal 11D-23-692	PR

**General Comment:**

CECMC Audit Report Summary

On 5/13/2025 at approximately 12:35, Compliance Inspector Matthew Morris conducted a follow-up audit at TEP ROCKY MOUNTAIN LLC, Dixon Federal Pad (SWNW-23-692)/11A-23-692 at Location ID #425899 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Staining in tank containment
- 2) Stored equipment on location

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored equipment/truck on location.		
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.		Date: 03/25/2025
Type	OTHER		
Comment:	Staining in tank containment.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.		Date: 05/29/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	OTHER		
Comment:	Pig station protected by pipe rails.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Bird Protectors	# 13		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 13		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 13		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	<p>Chemical tanks</p> <p>Equipment not listed in operators FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules.</p> <p>If operator remains out of compliance corrective action may be issued in future inspections.</p>		
Corrective Action:		Date:	
Type: Bradenhead	# 13		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	500 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	500 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID:	425882	Type:	WELL	API Number: 045-21098 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	425883	Type:	WELL	API Number: 045-21099 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	425884	Type:	WELL	API Number: 045-21100 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	425886	Type:	WELL	API Number: 045-21101 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	425888	Type:	WELL	API Number: 045-21103 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	425890	Type:	WELL	API Number: 045-21104 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	425892	Type:	WELL	API Number: 045-21105 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	425894	Type:	WELL	API Number: 045-21107 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<b>Producing Well</b>									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	425895	Type:	WELL	API Number:	045-21108	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	425897	Type:	WELL	API Number:	045-21109	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	425898	Type:	WELL	API Number:	045-21110	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	425900	Type:	WELL	API Number:	045-21111	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	425902	Type:	WELL	API Number:	045-21112	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Check Dams				
		Gravel				
		Compaction				
Rip Rap						
				Material Handling And Spill Prevention		
		Ditches				
Ditches						
Tackifiers						
		Culverts				
Gravel						
Compaction						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404202852	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7048148">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7048148</a>
708303805	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7048146">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7048146</a>