

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2025

Submitted Date:

05/13/2025

Document Number:

710500489

FIELD INSPECTION FORMLoc ID 311983 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Zeches, Giena	719-220-4041	gzeches@ogrisop.com	
Baca, Dave		dbaca@ogrisop.com	
Serna, Abe		abe.serna@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265527	WELL	PR	12/23/2005	CBM	071-07778	GOLDEN EAGLE 28-7	EI
283708	WELL	SI	03/20/2025	GW	071-08732	GOLDEN EAGLE 28-7X	EI
292693	PIT	AC			-	GOLDEN EAGLE 28-07X	EI
292694	PIT	AC			-	GOLDEN EAGLE 28-07	EI

General Comment:

This is an Environmental Inspection for the Golden Eagle 28-7 X well location located in Las Animas County Colorado. Remediation Project # 39701

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Well Placards located on meter house		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
Other	WELLHEAD			
Comment:	At the time of inspection, there was a grey material adjacent to the wellhead.			
Corrective Action:	Report spill or release of E&P waste or produced fluids in accordance with Rule 912.b. Contact ECMC EPS staff per Rule 912.b.			Date: 05/15/2025

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 265527	Type: WELL	API Number: 071-07778	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 283708	Type: WELL	API Number: 071-08732	Status: SI	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 292693	Type: PIT	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 292694	Type: PIT	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Environmental	
Spill/Remediation:	
Comment:	<div>This is an Environmental inspection for Remediation Project # 39701. Operator shall continue quarterly reporting until the site meets Table 915-1 standards.</div>
Corrective Action:	<div></div> <div>Date: <div></div></div>
Emission Control Burner (ECB): <div></div>	
Comment:	<div></div>
Pilot: <div></div>	Wildlife Protection Devices (fired vessels): <div></div>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water

Lined:

Pit ID: 292693Lat: 37.146720Long: -104.890000Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment:

At the time of inspection, there was no evidence of Pit Facility ID 292693 on location. ECMC records do not reflect a Form 4 or Form 27 for pit closure activities.

Operator shall provide evidence Pit was closed in accordance with regulations at the time of closure. If no historical records are available the Operator Shall investigate and close the Pit in accordance with Rule 911. and Rule 913, Under Remediation Project # 39701.

Corrective Action: Date: **Fencing:**

Fencing Type:

Fencing Condition:

Comment: Corrective Action: Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Action: Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment: Corrective Action: Date: Type: Produced WaterLined: NOPit ID: 292694Lat: 37.146620Long: -104.889900Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action: Date: **Fencing:**

Fencing Type:

Fencing Condition:

Comment: Corrective Action: Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

Monitoring:

Monitoring Type

Comment

Pit Level

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404202693	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047907
710500490	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047886