

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404210971

Date Received:
05/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____
Additional Operator Contact:
Contact Name Phone Email
Dolezal, Pat 970-332-3585 pat.dolezal@ownresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 698603325
Inspection Date: 03/13/2025 FIR Submit Date: 03/20/2025 FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC Company Number: 10699
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 303547

Location Name: BROPHY, T-64N46W Number: 31SWNW County: YUMA
Qtrqtr: SWN Sec: 31 Twp: 4N Range: 46W Meridian: 6
W
Latitude: 40.274190 Longitude: -102.562820

FACILITY - API Number: 05-125-00 Facility ID: 253268

Facility Name: BROPHY, T Number: 50-31
Qtrqtr: SWN Sec: 31 Twp: 4N Range: 46W Meridian: 6
W
Latitude: 40.274190 Longitude: -102.562820

CORRECTIVE ACTIONS:

1 CA# 203511
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Date: 04/20/2025
Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.
Response: CA COMPLETED Date of Completion: 03/26/2025
Operator Comment: Check valve was replaced. Operator has photos but unable to attach

ECMC Decision: _____

ECMC Representative: _____

2 CA# 203512

Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).

Date: 04/20/2025

Response: CA COMPLETED

Date of Completion: 04/08/2025

Operator Comment: Meter has been calibrated

ECMC Decision: _____

ECMC Representative: _____

3 CA# 203513

Corrective Action: Operators will promptly investigate, and if appropriate, repair, replace, or remediate any malfunctioning equipment or process. Comply with Rule 609.a. 15 days. If leak is found Immediate call to operator 24 hours to fix the leak or isolate leak.

Date: 03/14/2025

Response: CA COMPLETED

Date of Completion: 03/26/2025

Operator Comment: Check valve was replaced. Operator has photos but unable to attach

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal

Signed: _____

Title: Regulatory Specialist

Date: 5/20/2025 1:23:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files