

Inspection Photos

API: 017-07718

Operator: **VECTA OIL & GAS LTD**

Inspection Date: 5/19/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the access road which has revegetated.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing north at the location. The cattleguard has not been removed from the location. The perimeter fence was removed but not the cattleguard.



Inspection Photos



Photo 3. Center of the location facing north. Perennial vegetation is progressing throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Center of the location facing west. Perennial vegetation is progressing throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Center of the location facing south. Perennial vegetation is progressing throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Center of the location facing east. Perennial vegetation is progressing throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources