

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2025

Submitted Date:

05/20/2025

Document Number:

719000088

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325466 _____ GARCIA, CHARLES _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 10133 _____
Name of Operator: HILCORP ENERGY COMPANY _____
Address: P O BOX 61229 _____
City: _____ HOUSTON _____ State: _____ TX _____ Zip: _____ 77208 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,		FarmingtonRegulatoryTechs@hilcorp.com	All Inspections 6/21/2022

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214812	WELL	PR	06/11/2001	CBM	067-06416	TIFFANY C 1	PR
419641	WELL	PR	12/14/2010	CBM	067-09838	TIFFANY 2 3	PR

General Comment:

Inspection Report Summary
On 5/19/25 | Inspector Charles Garcia conducted an on-site inspection.
Location: TIFFANY C #1 API# 067-06416
TIFFANY #2-3 API# 067-09838
Operator:HILLCORP ENERGY COMPANY
County: LaPlata

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGNS AT WELLHEADS		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	505-324-5170 911 EMERGENCY	
Corrective Action:		Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	OIN TANKS FOR PRIME MOVERS WITH SPILL PREVENTION ON C #1 #2-3 TANK HAS NO SPILL PREVENTION		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	4 MARKERS ARE ON GROUND		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		

Comment:	METER HOUSE LAST CALIBRATION TIFFANY C #1 NO CARD FOUND TIFFANY #2-3 1/27/25			
Corrective Action:	PROVIDE CALIBRATION RECORD FOR TIFFANY C #1		Date:	06/20/2025
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	
Type: Other	# 2			
Comment:	WELLHEADS			
Corrective Action:			Date:	
Type: Pump Jack	# 2			
Comment:				
Corrective Action:			Date:	
Type: Prime Mover	# 2			
Comment:	GAS			
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 214812 Type: WELL API Number: 067-06416 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 06/19/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419641 Type: WELL API Number: 067-09838 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 06/19/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000095	location pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057965