

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2025

Submitted Date:

05/20/2025

Document Number:

717701407

FIELD INSPECTION FORM

Loc ID: 448946 Inspector Name: Burns, Adam On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10649
Name of Operator: EWS 4 DJ BASIN LLC
Address: 2015 CLUBHOUSE DR SUITE 201
City: GREELEY State: CO Zip: 80634

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beasley, Nolan		nolan.beasley@state.co.us	
Gage, Dave		Dgage@expedition-water.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486708	TANK BATTERY	AC	05/15/2024		-	EWS Facility 4 Tank Battery	AC

General Comment:

This is an annual audit on the UIC Facility

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		Date: _____
Corrective Action:			

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 2		
Comment: Sump Pumps			
Corrective Action:		Date:	
Type: Progressive Cavity	# 3		
Comment: Injection Pumps			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 4		
Comment: Unloading Pumps			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	OTHER	LVST		40.136400,-104.466400
Comment:	Produced Water/ Oil Tank Separation Tanks				
Corrective Action:					Date:

<u>Paint</u>	
Condition	Adequate
Other (Content)	
Other (Capacity)	750 BBLs
Other (Type)	

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

<u>Paint</u>	
Condition	
Other (Content)	
Other (Capacity)	750 BBLs
Other (Type)	

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

<u>Paint</u>	
Condition	Adequate
Other (Content)	
Other (Capacity)	750 BBLs
Other (Type)	

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	20	OTHER	FIBERGLASS AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	750 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 486708 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: [Active UIC Facility](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717701408	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7057961