

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2025

Submitted Date:

05/20/2025

Document Number:

719000089

FIELD INSPECTION FORMLoc ID 306777 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		FarmingtonRegulatoryTechs@hilcorp.com	All Inspections 6/21/2022
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264203	WELL	PR	02/01/2022	CBM	067-08737	TIFFANY 1R	PR

General Comment:

Inspection Report Summary
On 5/19/25 I Inspector Charles Garcia
conducted an on-site inspection.
Location: TIFFANY 1R
Operator:HILCORP ENERGY COMPANY
API#: 067-08737
County: LaPlat

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	WELL SIGN AT ENTRANCE OF LOCATION		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	505-324-5170 911 EMERGENCY	
Corrective Action:		Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	CATTLE PANELS SOUND WALLS		
Corrective Action:		Date:	

Equipment:

Type:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	3 UNMARKED		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	GAS		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELL HEAD HAS PACKING LEAK PRODUCED WATER COMING OUT		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	METER HOUSE LAST NO CALIBRATION CARD FOUND		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	OIL TANK FOR PRIME MOVER WITH SPILL PREVENTION		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	264203	Type:	WELL	API Number:	067-08737	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	06/12/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	1	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000096	LOCATION PICS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7058314