

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2025

Submitted Date:

05/20/2025

Document Number:

719000091

FIELD INSPECTION FORMLoc ID 334046 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10755

Name of Operator: MORNINGSTAR OPERATING LLC

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270217	WELL	PR	01/13/2005	GW	067-08899	DUELL 32-6 5-2	PR
293846	WELL	PR	12/05/2007	GW	067-09456	DUELL 32-6 5-4	PR

General Comment:

Inspection Report Summary
 On 5/19/25 I Inspector Charles Garcia
 conducted an on-site inspection.
 Location: DUELL #6-2
 DUELL 32-6 5-4
 Operator: MORNINGSTAR OPERATING LLC
 API#: 067-09456
 County: LaPlat

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGNS AT WELLHEAD		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

 Comment: 1-844-487-3549
 911 EMERGENCY

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	4FT HOG WIRE		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	8FT CHAINLINK		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	8FT CHAIN LINK		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:		CHEMICAL INJECTION TANK WITH SPILL PREVENTION		Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:		TELEMETRY EQUIPMENT		Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:		ELECTRIC PANELS		Date:	
Corrective Action:				Date:	
Type: Other	# 2				
Comment:		WELLHEADS		Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Prime Mover	# 2				
Comment:		ELECTRIC		Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Other	# 2				
Comment:		METER HOUSES LAST CALIBRATION 2/19/25 BOTH WELLS		Date:	
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 2				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	PBV STEEL		37.048840,-107.528090
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	270217	Type:	WELL	API Number:	067-08899	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		10/30/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		85		Fluid Type: NONE			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	293846	Type:	WELL	API Number:	067-09456	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		10/30/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		65		Fluid Type: NONE			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000098	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7058376