

Inspection Photos

API: 017-07031

Operator: ANADARKO E&P ONSHORE LLC

Inspection Date: 5/19/2025

County: CHEYENNE



Inspection Photos



Photo 1. The fence at the entrance has not been installed back to the original position.



Inspection Photos



Photo 2. Facing south toward the former access road which has revegetated.



Inspection Photos



Photo 3. Facing east at the north side of the location. It appears this area was recently drill seeded due to visible drill rows. There was some germination observed.



Inspection Photos



Photo 4. Facing east at the northeast side of the location. It appears this area was recently drill seeded due to visible drill rows. There was some germination observed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 5. Center of the location facing north..



Inspection Photos




Photo 6. Center of the location facing south.

