

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2025

Submitted Date:

05/15/2025

Document Number:

693808645

**FIELD INSPECTION FORM**Loc ID 316828 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10841

Name of Operator: AMERICAN HELIUM LLC

Address: 23501 CINCO RANCH BLVD, B244

City: KATY State: TX Zip: 77494

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                       | Comment         |
|------------------|--------------|-----------------------------|-----------------|
| Browning, Chuck  | 970-433-4139 | chuck.browning@state.co.us  | Field Inspector |
| Joyner, Ryan     | 970.385.6289 | rjoyner@blm.gov             | Tres Rios       |
| Labowskie, Steve |              | steve.labowskie@state.co.us |                 |
| Lapham, Ken      | 979-877-4951 | klapham@americanhelium.us   | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name             | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 263697      | WELL | PR     | 07/01/2024  | GW         | 113-06102 | ANDY'S MESA FEDERAL<br>27 | SI          |

**General Comment:**

ECMC staff performed a routine field inspection on 5/12/2025.  
 No issues were found requiring corrective action. See inspection text and photos for details.  
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Main   |       |  |
| comment:          |        |       |  |
| Corrective Action | L      | Date: |  |
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action | L      | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | TANK LABELS/PLACARDS                    |       |            |
| Comment:           | Tank labels faded and illegible         |       |            |
| Corrective Action: | Install sign to comply with Rule 605.g. | Date: | 06/16/2025 |
| Type               | WELLHEAD                                |       |            |
| Comment:           | Sign on meter housing                   |       |            |
| Corrective Action: |   | Date: |            |

**Emergency Contact Number:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Comment:           | 435-631-2239 |       |  |
| Corrective Action: |              | Date: |  |

Overall Good: ☒**Spills:**

|  |      |        |  |  |
|--|------|--------|--|--|
| Type   | Area | Volume |  |  |
| In Containment:  | No   |        |  |  |
| Comment:   |      |        |  |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |  |

**Fencing/:**

|                    |             |       |  |
|--------------------|-------------|-------|--|
| Type               | WELLHEAD    |       |  |
| Comment:           | Panel fence |       |  |
| Corrective Action: |             | Date: |  |

**Equipment:**

|                                   |  |       |                 |
|-----------------------------------|--|-------|-----------------|
|                                   |  |       | corrective date |
| Type: Horizontal Heated Separator | # 1  |       |                 |
| Comment:                          | Separators disconnected and blind flanged by BLM |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Plunger Lift                | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Gas Meter Run               | # 1  |       |                 |
| Comment:                          |  |       |                 |

|                          |     |       |  |
|--------------------------|-----|-------|--|
| Corrective Action:       |     | Date: |  |
| Type: Deadman # & Marked | # 4 |       |  |
| Comment:                 |     |       |  |
| Corrective Action:       |     | Date: |  |
| Type: Bradenhead         | # 1 |       |  |
| Comment:                 |     |       |  |
| Corrective Action:       |     | Date: |  |
| Type: Bird Protectors    | # 1 |       |  |
| Comment:                 |     |       |  |
| Corrective Action:       |     | Date: |  |

**Tanks and Berms:**

|                    |   |           |           |         |                       |  |
|--------------------|---|-----------|-----------|---------|-----------------------|--|
| Contents           | # | Capacity  | Type      | Tank ID | SE GPS                |  |
| CONDENSATE         | 1 | <100 BBLS | PBV STEEL |         | 38.046354,-108.642025 |  |
| Comment:           |   |           |           |         |                       |  |
| Corrective Action: |   |           |           |         | Date:                 |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities   |        |       |      |             |           |         |    |               |    |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 263697 | Type: | WELL | API Number: | 113-06102 | Status: | PR | Insp. Status: | SI |
| Idle Well  |        |       |      |             |           |         |    |               |    |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |       |      |             |           |         |    |               |    |
| Comment: <span style="color: blue;">Tubing valve locked out by BLM.</span>   |        |       |      |             |           |         |    |               |    |
| Corrective Action: _____ Date: _____   |        |       |      |             |           |         |    |               |    |
| BradenHead   |        |       |      |             |           |         |    |               |    |
| Date of Last Brhd Test: 05/05/2025      Annual Brhd Completed? Yes   |        |       |      |             |           |         |    |               |    |
| Last Brhd Test Results      Initial Surf Csg Pressure: 0      Fluid Type: NONE   |        |       |      |             |           |         |    |               |    |
| End Surf Csg Pressure: 0   |        |       |      |             |           |         |    |               |    |
| Comment: _____   |        |       |      |             |           |         |    |               |    |
| Corrective Action: _____ Date: _____   |        |       |      |             |           |         |    |               |    |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12                                 |        |       |      |             |           |         |    |               |    |

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 404206512    | INSPECTION SUBMITTED        | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051511">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051511</a> |
| 693808646    | Inspection photos 5/12/2025 | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051489">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7051489</a> |