

WGS84  
±16ft

40.13453, -104.90973

m  
±4m

1514

°T  
±10

NE33



ECMC  
Environmental  
Field Inspection



Miller 33-17J  
© 14-May-25 10:27:16 AM  
ECMC Environmental Inspection

Former tank battery location. Meter house remains on location.

WGS84  
±10ft

40.13495, -104.90955

m  
±3m

1514

°T  
±11

N349



Miller 33-17J  
© 14-May-25 10:28:17 AM  
ECMC Environmental Inspection

ECMC  
Environmental  
Field Inspection



Unmarked soil stockpile was observed on location with no stormwater BMPs. No liner was visible.

WGS84  
±15ft

40.13502, -104.90967

$\Delta$  <sup>m</sup>  
±4m

1513

$\nabla$  °,T  
±11

N4



Miller 33-17J  
© 14-May-25 10:28:50 AM  
ECMC Environmental Inspection

ECMC  
Environmental  
Field Inspection



Ruts are visible at the approximate spill location. The produced water vessel excavation has been backfilled.