

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2025

Submitted Date:

05/22/2025

Document Number:

717100205

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Rollins, Grace _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspection
Graber, Nikki		nikki.graber@state.co.us	
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
490088	SPILL OR RELEASE	CL	05/05/2025		-	Miller 33-17J	EI

General Comment:

ECMC Environmental Field Inspection Report Summary
This is an environmental inspection to determine progress on Spill ID 490088 and Remediation Project # 39263. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 490088
Spill Name: Miller 33-17J
Remediation Project #: 39263
Location ID: 319620
Reported Date of Discovery: 05/01/2025
Date of Inspection: 05/14/2025

Spill is located within or adjacent to:
-Town of Firestone (within)
-Livestock (~190 ft northwest)
-Residential building units (~340 ft west)

Current site status:
-Excavations have been backfilled at the former tank battery.
-Meter house remains on location.
-Ruts are visible at the approximate location of the former produced water vessel excavation.
-An unmarked soil stockpile was observed on location with no stormwater BMPs. No liner was visible.

See attached corrective actions. A Supplemental Form 27 is required.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 490088 CDP: _____

Comment: Ruts are visible at the approximate location of the former produced water vessel excavation.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 490088 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation Project # 39263 was created for decommissioning of the MILLER-62N67W 17SWSE facility, the plugging and abandonment of the MILLER 33-17 J wellhead, and decommissioning of the MILLER 33-17 J, MILLER 44-17J, and MILLER 34-17 J flowlines. Excavations have been backfilled at the former tank battery. Quarterly reporting is required under Remediation Project # 39263; the last Form 27 for this project was submitted 02/06/2025 (Document Number 404063372).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project # 39263.

Date: 06/05/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: An unmarked soil stockpile was observed on location with no/inadequate stormwater BMPs. No liner was visible.

Corrective Action: Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100206	ECMC Photo Log - Miller 33-17J - 05.14.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7061233