

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2025

Submitted Date:

05/22/2025

Document Number:

719000110

FIELD INSPECTION FORM

Loc ID 326264 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Findings:

- 15 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Huntington, Heather		hhuntington@enduringresources.com	SJB inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Walter, Klye		kwalter@enduringresources.com	SJB inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216136	WELL	PR	03/08/2002	CBM	067-07742	CHANEY 1-1	PR

General Comment:

[Inspection Report Summary](#)
On 5/22/25 | Inspector Charles Garcia conducted an on-site inspection.
Location: CHANEY 1-1
Operator: ENDURING RESOURCES
API#: 067-07742
County: LaPlata

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE OF LOCATION		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	1-800-916-7897 911 EMERGENCY	
Corrective Action:		Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	6FT CHAIN LINK		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	CHEMICAL INJECTION SYSTEM WITH SPILL PREVENTION		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	ELECTRIC PANELS		
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	GAS GENERATOR		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	TELEMETRY EQUIPMENT		Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	ELECTRIC		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 0			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	LUBE OIL CONTAINER FOR GAS GENERATOR WITH SPILL PREVENTION		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	METER HOUSE LAST CALIBRATION 5/21/25		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	WELLHEAD		Date:	
Corrective Action:			Date:	

Venting:

Yes/No	NO	Date:	
Comment:			Date:
Corrective Action:			Date:

Flaring:

Type		Date:	
Comment:			Date:
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000111	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7062066