

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2025

Submitted Date:

05/16/2025

Document Number:

701104182

FIELD INSPECTION FORMLoc ID 324139 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 3 GREENWAY PLAZA STE 1360

City: HOUSTON State: TX Zip: 77046

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wheeler, Steven		steven.wheeler@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
, COGCC		aaron.trujillo@state.co.us	
Smelser, Wayne		wayne.smelser@state.co.us	
, Mustang		nwelch@venatorresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258987	WELL	PR	07/01/2024	GW	045-07675	SAVAGE 11-35-6-94 W	EG

General Comment:

Flowline Integrity Inspection on Tuesday 5/13/25 and Wednesday 5/14/25
 Flowline excavated for the Burns 9-35-6S-94W to be cut and capped for flowline abandonment.
 Risers and meter house on location after abandonment of Burns 9-35-6S-94W flowline.
 Comply with Rule 606 by June 30, 2025

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Risers and meter house on location after abandonment of Burns 9-35-6S-94W flowline.			
Corrective Action:	Comply with Rule 606			Date: 06/30/2025
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities

Facility ID: 258987 Type: WELL API Number: 045-07675 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404208260	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7054083
701104183	Flowline integrity inspection 701104182 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7054079