

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2025

Submitted Date:

05/16/2025

Document Number:

701104184

**FIELD INSPECTION FORM**

Loc ID 324144 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10550  
Name of Operator: MUSTANG RESOURCES LLC  
Address: 3 GREENWAY PLAZA STE 1360  
City: HOUSTON State: TX Zip: 77046

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone | Email                         | Comment |
|--------------------|-------|-------------------------------|---------|
| , Mustang          |       | nwelch@venatorresources.com   |         |
| Trujillo, Aaron    |       | aaron.trujillo@state.co.us    |         |
| Smelser, Wayne     |       | wayne.smelser@state.co.us     |         |
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us |         |
| Wheeler, Steven    |       | steven.wheeler@state.co.us    |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 259159      | WELL | SI     | 04/01/2022  | GW         | 045-07696 | BURNS 9-35-6-94 W | EG          |

**General Comment:**

Flowline Integrity Inspection on Tuesday 5/13/25 and Wednesday 5/14/25  
Wellhead and flowlines being abandoned for the Burns 9-35-6S-94W  
Wellhead, separator, tank, stair case, flowline risers on location. Pipe cut out of creek laying on west and east sides of the creek.  
Comply with Rule 606 by June 30, 2025

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: UNUSED EQUIPMENT

Comment: Wellhead, separator, tank, stair case, flowline risers on location. Pipe cut out of creek laying on west and east sides of the creek.

Corrective Action: **Comply with Rule 606**

Date: 06/30/2025

Overall Good:

**Spills:**

| Type | Area | Volume |
|------|------|--------|
|      |      |        |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 259159 Type: WELL API Number: 045-07696 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                                    | URL   |
|--------------|--|---|
| 404208262    | INSPECTION SUBMITTED                           | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7054084">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7054084</a> |
| 701104185    | Flowline integrity inspection 701104184 photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7054080">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7054080</a> |