

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2025

Submitted Date:

05/23/2025

Document Number:

698603630

**FIELD INSPECTION FORM**

Loc ID 303554 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253281	WELL	PR	12/30/1999	GW	125-07158	W. KORF 3	PR

**General Comment:**

Inspector completed Follow-up inspection 05/20/2025 as required by FIR to ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 02/28/25 FIR document number 698603209. Operator has submitted FIRR. All corrective actions identified in FIR has been completed.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign at wellhead location. Sticker over previous operator information is peeling and requires replacement.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Previous FIR CA - Content/Quantity/Hazard sign at produced water tank is faded and unreadable. CA Completed.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Emergency contact information posted on Lease sign.		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Tubing in the wellbore. Tubing valve open. Casing valve not connected.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 253281 Type: WELL API Number: 125-07158 Status: PR Insp. Status: PR

**Producing Well**

Comment: Tubing valve open. Casing valve not connected. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.

Electronic Well File reflects last Production/Status reported 3/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603639	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7062922">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7062922</a>