

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2445 From entrance to location



Photo # 2446 From entrance to location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2447 Location



Photo # 2448 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2449 Location



Photo # 2450 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2451 Location



Photo # 2452 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2453 Location



Photo # 2454 Unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2455 Same unmarked deadman



Photo # 2456 Same unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202




Photo # 2457 GIBSON GULCH UNIT 6-29 well BH line connected to flowline



Photo # 2458 GIBSON GULCH UNIT 6-29 well BH line connected to flowline

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2459 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut



Photo # 2460 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2461 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut



Photo # 2462 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2463 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut



Photo # 2464 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2465 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut



Photo # 2466 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2467 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut



Photo # 2468 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2469 GIBSON GULCH UNIT 6-29 well - Ball valve on line connecting BH line to flowline appears to be shut



Photo # 2470 Unused hose in secondary containment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Photo # 2471 Debris



Photo # 2472 Debris